



Product Change Notice

Product Change Notification Number: Fido5100-A

Title: fido5100 Rev. 2

Date of Notification: 10/14/14

Samples Available: Immediately

Effective Date: 10/14/2014

This Change Affects Innovasic Part Numbers

fido5100 Rev 1 chipset

Description of Change: The fido5100 chipset is comprised of an FPGA, the fido5000 and a memory containing the program file, the f0101. The fido5100 chipset has been upgraded to support Profinet version 2.3. As a result, the fido5100 chipset is now at revision 2 and the memory chip part number has been changed to f0102. The fido5000 is unaffected by this change.

Impact of Change to the Customer: None. However, the revision 2 chipset is required to support Profinet beyond v2.2.5.

PCN Revision History:

<u>Revision</u>	<u>Date</u>	<u>Reason for Change</u>
A	10/14/14	Hardware change to support Profinet version 2.3

For More Information:

Tom Weingartner	505-883-5263 x-122	tweingartner@innovasic.com
------------------------	---------------------------	-----------------------------------

IMPORTANT NOTICE

CUSTOMER RESPONSE FOR ACCEPTANCE OR CONCERNS IS EXPECTED WITHIN 10 DAYS OF THE NOTICE. IN ORDER TO MINIMIZE RISKS ASSOCIATED WITH THE CUSTOMER'S APPLICATIONS, ADEQUATE DESIGN AND OPERATING SAFEGUARDS MUST BE PROVIDED BY THE CUSTOMER TO MINIMIZE INHERENT OR PROCEDURAL HAZARDS.

CERTAIN APPLICATIONS USING SEMICONDUCTOR PRODUCTS MAY INVOLVE POTENTIAL RISKS OF DEATH, PERSONAL INJURY OR ENVIRONMENTAL DAMAGE. INNOVASIC PRODUCTS ARE NOT DESIGNED, WARRANTED OR AUTHORIZED TO BE SUITABLE FOR USE IN LIFE-SUPPORT DEVICES, SYSTEMS OR OTHER CRITICAL APPLICATIONS. INCLUSION OF INNOVASIC PRODUCTS IN SUCH APPLICATIONS IS TO BE FULLY AT THE CUSTOMER'S RISK.